



Important Notice – 31/07/25

Alliance Environmental Services Ltd (AES Ltd) in conjunction with Cheshire East Bereavement Services (CEBS) on behalf of High Peak Borough Council..

AES Ltd are carrying out a safety survey of the memorials in **St Georges, New Mills**

We are responsible to ensure the safety of all visitors to the cemeteries under our control and following fatalities and injuries in other parts of the country caused by falling memorials, we are following advice by the Health and Safety Executive the Ministry of Justice and the Diocesan Advisory Committee. This churchyard is subject to the Faculty Jurisdiction of the Church of England, exercised through the Consistory Court.

During our latest survey we identified the memorials below have failed the testing and in need of remedial work:

The large, stepped cross / pinnacle memorial:

	ANDERTON, Willie – 12/12/1890 / ANDERTON, James 01/12/1934
E4	GREENWOOD, FRANCES/AGNES
H3	PITCHER, ALEX
I4	WOODALL, REUBEN/MARGARET 1895-1986
D3	FROST, WILLIAM/RAMSBOTTOM, MARGARET 1903-1974
H5	TAYLOR, JOHN 12/10/71
I6	WHITTLE, CHARLES/DORRIS 21/02/72
I7	HUDDLESTONE, SAMUEL/MARGARET 18/02/1983
J5	HINCHCLIFFE, BENJAMIN
M4	IBBOTSON, FRED/ELSIE
V1	BAILEY, WINFRED/HILDA 01/03/2003
X1	QUATE, JOHN/CLOVER 02/08/1989
ZZ1	BAILEY, GEORGE 28/07/1980
YY3	BATES, MARIAN/SQUIRE 13/07/1983
YY4	SMITH, BEATRICE/THOMAS 26/05/1985
WW6	MARCHINGTON, JOHN/FREDA
VV5	BURGON, GLADYS 20/01/1982
TT4	CHATTERTON, BERTRAM/KATHLEEN
TT6	MEALOR, KATHLEEN/ERIC 1915 - 1984
SS5	FORSYTH, GORDON
E9	BENSTEAD, KARIN 08/02/1982
G9	DOWNES, LESLEY ANN 05/01/1993
I10	CRANKSHAW, EDWIN/JESSIE 13/09/1970
K25	HILL, JESSIE/ANN 13/02/1952
R1	WARHURST, FLORENCE/ARNOLD 13/07/1985
R2	WOOD, DAVID 07/11/1947
S10	HARTLE, THOMAS/JOSEPH 24/04/1939
B41	SWEATCOMBE, JOHN
C34	LONG, & MOSS, ETHEL
C37	BROADBENT, ALICE 03/08/1925
C38	CHAPPELL, MARION

H55 ASHWORTH, MARGARET
I36 KNIGHT, GEORGE/FLORENCE 04/08/1953
S36 SECOMBE, JAMES March 1910
T37 NO NAME
U38 NO NAME
South section JACKSON, THOMAS/ELLEN 11/02/1924

The primary responsibility for maintenance of the memorial rests with the owner of the memorial. We require to know if the owners intend to carry out the essential remedial work's required.

If we do not hear from the owners by **28/08/25** then it will be assumed that you do not wish to carry out the work and CEBS will then arrange for the necessary works to make the memorial safe. This work will be conducted at a cost however we will seek to recoup that cost from the owner.



Cemetery Office, 87 Prestbury Road, Macclesfield, Cheshire, SK10 3BU

alliancecemeteries@cheshireeast.gov.uk Telephone - 01625 383945

OFFICIAL